

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 8585	LOCATION 2928 P.M.			
DATE 9/15/31	PURPOSE Repair Wood Shingles			
ZONE Multi-Fam	OWNER Geo Hansen			
	ARCH'T Olin Barber			
	CONT-R Olin Barber			
VAL. 100 -	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
9/21/51	Re-Shingling of Roof of Dory with Cedar Shingles Completed Alder Campbell
9/21/51	COMPLETE AND O.K. Alder Campbell INSPECTOR