

R-219-F551

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00

TYPE BUILDINGS

PERMIT NO.					
E-7796		LOCATION		2016-2020 - 17th Street A-2	
DATE		PURPOSE			
June 30-67		Repair pest damage to duplex			
ZONE		OWNER		M. Machado Same	
		ARCH'T		No Phone	
		CON'TR Midstate Termite P.O. Box 8827			
VAL. \$400.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM	7-6-67	Chapin			
JOIST					
FRAME					
SHEET					
ROCK					
FINAL	7-11-68	E. Hammond		4-3-68	e.k.



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
2-11-47	Placed Cleanup across concrete a fine crack in front porch at 2030-17 St. C. Mason
4-2-48	Send notice of no pipe ^{Wanna}
4-2-48	Demolish into front no address front door porch these cracks have both sides but none not finished 4-7-48 ^{Chapin}
COMPLETE AND OK	INSPECTOR

