

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11260</i> DATE <i>5/13/43.</i> ZONE	LOCATION	<i>2922 - Oct.</i>
	PURPOSE	<i>Repairs to porch new foundation.</i>
	OWNER	<i>John Perry.</i>
	ARCH'T.	
	CONTR.	<i>Frank Jena</i>

VAL. <i>190⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>-</i>	APTS.	SIZE
------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
5/14/43	1 ST / NSP. Forms for new Concrete Foundation under old dwg. ^{OK} A.W. Campbell
5/20/43	2 ND / NSP. Frame for Porches ^{OK} A.W. Campbell
5/23/43	3 RD / NSP. PATCHING OF PLASTERING ^{OK} A.W. Campbell
6/25/43	4 TH / NSP. Repairs Completed ^{OK}
6/28/43	<div style="display: flex; justify-content: space-between; align-items: center;"> COMPLETE AND O. K. Alden W. Campbell INSPECTOR </div>