

*R291 F102-104*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**\$23.00**

**TYPE BUILDINGS**

PERMIT NO. <b>S-6718</b>		LOCATION <b>3850 - Florin Road</b>		A-5	
DATE <b>11-12-70</b>		PURPOSE <b>Construct sign</b>			
ZONE		OWNER <b>Florin Toyota Corp.</b>		Same	
		ARCH'T			
		CONTR <b>Ad-Art Inc, P.O. Box 2308, Sacto.</b>			
VAL. <b>\$2,500.</b>		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (o) (c) <b>922-5671</b>
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL	<i>5-10-71</i>	<i>[Signature]</i>			<i>[Signature]</i>

1. The work shall be completed within the specified time frame.

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<b>COMPLETE AND OK</b>

**INSPECTOR**