

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-367v</i>	LOCATION <i>1055 - Perkins Way</i>
DATE <i>8/22/39</i>	PURPOSE <i>Erect new dwlg. gar.</i>
ZONE <i>v-7am</i>	OWNER <i>Jack Rohlt</i>
	ARCH'T. <i>A. J. Fisher</i>
	CON'T.R. <i>A. J. Fisher</i>
VAL. <i>5000⁰⁰</i>	STORIES <i>1</i> ROOMS <i>5</i> APTS. SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i> <i>1160^{sq} @ 350</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK - REMARKS
8/29/39	1 st Insp Ferrus & Rust
9/8/39	2 nd Insp. Furnace in place ^{OK} A.W. Campbell
9/21/39	3 rd Insp. INT & EXT TANK ^{OK} A.W. Campbell
11/9/39	4 th Insp. Drip & Garage Completed
" "	Issued Final Insp. & Cert. of Occy.
" "	Stack cleaned up OK
11/9/39	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. A.W. Campbell INSPECTOR </div>