

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5474</i>	LOCATION <i>1175 - Resena Way</i>
DATE <i>1/5/37</i>	PURPOSE <i>New dwlg &amp; garage</i>
ZONE <i>1</i>	OWNER <i>E. E. Ruby</i>
	ARCH'T. <i>E. E. Ruby</i>
	CONTR. <i>E. E. Ruby</i>

VAL. <i>7700<sup>00</sup></i>	STORIES <i>2</i>	ROOMS <i>7</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	<i>2200<sup>PI</sup></i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 350</i>
LATH		GAS VENTS	<i>1</i>
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
1/8/37	1 <sup>ST</sup> WSP. Forms in place <sup>OK</sup> A.W. Campbell
2/5/37	2 <sup>ND</sup> WSP. Frame " " <sup>OK</sup> A.W. Campbell
2/16/37	3 <sup>RD</sup> WSP. INT + EXT LATH <sup>OK</sup> A.W. Campbell
COMPLETE AND O. K.	INSPECTOR