

1596 7547563

Ptn. C BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$174.50

Riverside Estates TYPE BUILDINGS

|                            |                     |   |                               |  |
|----------------------------|---------------------|---|-------------------------------|--|
| PERMIT NO.<br><b>E-761</b> | LOCATION            | <b>5700 - Riverside Blvd.</b>                   |                               | <b>A-3</b>                             |
| DATE<br><b>Mar. 9-62</b>   | PURPOSE             | <b>Const. 10-unit apartment house.</b>          |                               |  |
| ZONE<br><b>R-3</b>         | OWNER               | <b>DiPinto &amp; Jones Inc. 1921-Florin Rd.</b> |                               |  |
|                            | ARCH'T              | <b>Ken Venolia 5709-Freeport Blvd.</b>          |                               |  |
|                            | CONT'R              | <b>Owner Same GA 1-5507</b>                     |                               |  |
| VAL. <b>\$69,700.</b>      | STORIES<br><b>2</b> | ROOMS<br><b>40</b>                              | APTS.<br><b>10</b>            | 4,005-2nd SIZE<br><b>4,325 sq. ft.</b> |
| INSP.                      | DATE                | BLDG. TYPE<br><b>V</b>                          | OCCUPANCY GROUP<br><b>H-1</b> |  |
| FORM                       | <b>3-27-62</b>      | <i>Const</i>                                    |                               |  |
| JOIST                      | <b>4-9-62</b>       | <i>Const</i>                                    |                               |  |
|                            | <b>5-4-62</b>       | <i>Const (concrete)</i>                         |                               |  |
| FRAME                      | <b>5-15-62</b>      | <i>Const</i>                                    |                               |  |
| SHEET                      | <b>5-22-62</b>      | <i>Const (concrete)</i>                         |                               |  |
| ROCK                       | <b>5-17-62</b>      | <i>Const (concrete)</i>                         |                               |  |
| FINAL                      | <b>7-13-62</b>      | <i>Const</i>                                    |                               |  |

| DATE               | SPECIAL CONDITIONS OF WORK — REMARKS                 |
|--------------------|--|
| 1-26-62            | Lufs <i>Count</i>                                    |
| 5-7-62             | Lufs <i>Counting</i>                                 |
| 5-8-62             | No plans or drawings <i>Count</i>                    |
| 5-11-62            | Pt frame - not ready <i>Count</i>                    |
| 5-17-62            | Pt frame - does not match <i>Count</i>               |
| 7-11-62            | Pt Final - No stamped<br>Copy of plans on job Guller |
|                    |  |
|                    |  |
|                    |  |
| COMPLETE<br>AND OK | INSPECTOR  |