

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

| | | | | | |
|--------------------------|--|------------------|--|-------------------|--|
| PROPERTY PARCEL NO. | | JOB ADDRESS | | INSPECTION AREA | |
| 111 Breckenwood Way | | 1 | | FINAL INSPECTIONS | |
| LEGAL DESCRIPTION | | | | | |
| Sierra Oaks #15 Lot 508 | | | | | |
| TITLE AND NAME | | ADDRESS | | ZIP | |
| Bob Drongerer | | 222 Hathaway Ct. | | | |
| GEN. CONTR. | | CITY LIC. NO. | | TEL. NO. | |
| ELEC. CONTR. | | | | | |
| PLBG. CONTR. | | | | | |
| MECH. CONTR. | | | | | |
| ARCH. ENGR. | | | | | |
| OWNER | | D. R. Moore | | | |
| CONST. LOAN LENDER | | 99 Breckenwood | | | |
| CERTIFICATE OF OCCUPANCY | | ISSUED BY | | | |
| DATE | | DATE | | | |
| BLDG. WIDTH | | BLDG. LENGTH | | TOTAL HEIGHT | |
| | | | | | |
| NO. OF STORIES | | ROOF CONSTR. | | AREA 1st FLOOR | |
| | | | | TOTAL AREA | |
| | | | | C.S.D. | |
| | | | | C.I. CASE | |
| REAR YARDS | | SET BACK REQ. | | USE ZONE | |
| | | | | | |
| PARK'G. REQ. | | SPACES | | TREES RMVD. | |
| | | | | 2,498 | |
| EXISTING BLDG'S SAME LOT | | HOW USED | | CENSUS TRCT. NO. | |
| | | | | | |

NATURE OF WORK:- Const. dwelling and att. garage

| | | | |
|--------------------------|--|------------------|--|
| PERMIT NO. S.P. - | | H-2615 | |
| ISSUED BY | | MICROFILM RECORD | |
| ISSUANCE DATE | | 8-2-71 | |
| VALUATION | | \$ 37,000.00 | |
| R.O.F. FEE | | \$ | |
| JOB FILE | | REEL NO. 308 | |
| INSPECTION RECORD | | REEL NO. 390 | |
| FRAME NO. TO | | 399 | |
| FRAME NO. TO | | 301 | |
| S.M.I. FEE | | \$ | |
| PLAN CK. FEE | | \$ | |
| SEWER INCL. FEE | | \$ | |
| PERMIT FEE | | \$ 123.00 | |
| TOTAL FEES | | \$ | |
| REMARKS AND/OR VARIANCES | | Dwelling | |