

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5306</i>	LOCATION <i>1900 - 9th Street</i>
DATE <i>Nov. 27/36</i>	PURPOSE <i>Market</i>
ZONE <i>Gen Com.</i>	OWNER <i>Regman J. Davis</i>
	ARCH'T. <i>Chas. Dean</i>
	CONTR. <i>Peterson &amp; Steinheyer</i>

VAL. <i>15075<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>—</i>	APTS. <i>103-90</i>	SIZE
--------------------------------	---------------------	-------------------	------------------------	------

LIGHT SHAFTS	<i>Wrecked</i>	ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

"South Side Market Bldg"

DATE	CONDITION OF WORK-REMARKS
12/7/36	1 <sup>ST</sup> / HSP. Formwork in place <sup>OK</sup> A.W. Campbell
12/21/36	2 <sup>ND</sup> / HSP. Frame <sup>OK</sup> A.W. Campbell
1/28/37	3 <sup>RD</sup> / HSP. Int & Ext Latt. <sup>OK</sup> A.W. Campbell
3/28/37	4 <sup>TH</sup> / HSP. 1-Story Market Bldg Complete
	O.K. A.W. Campbell
3/28/37	COMPLETE AND O.K. <i>Arthur H. Campbell</i> INSPECTOR