

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>B-7615</b>	LOCATION <b>884 - Robertson Way</b>			
DATE <b>3/5/41</b>	PURPOSE <b>New dwlg. w/ gar</b>			
ZONE	OWNER <b>J. L. Blinett</b>			
	ARCH'T.			
	CONTR. <b>Owner</b>			
VAL. <b>4000<sup>00</sup></b>	STORIES <b>1</b>	ROOMS <b>5</b>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<b>area</b>	
VENT SHAFTS		BOILER ROOMS	<b>1117<sup>01</sup></b>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<b>@ 350</b>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS	<b>66</b>	
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
3/6/41	1 <sup>ST</sup> /NSP. Forms in place, <sup>OK</sup> R.W. Campbell
3/26/41	2 <sup>ND</sup> /NSP. Frame " " " " <sup>OK</sup> R.W. Campbell
4/7/41	3 <sup>RD</sup> /NSP. INT & EXT LATW <sup>OK</sup> R.W. Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="292 828 421 870">COMPLETE AND O. K.</span> <span data-bbox="1120 844 1249 870">INSPECTOR</span> </div>