

B-103F508-517

Lt. 4 **BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$46.00

Mayfair Gardens #7 TYPE BUILDINGS

PERMIT NO. E-1686	LOCATION	7370 - Nelmark Street		A-5
DATE Jul-2-62	PURPOSE	Const. dwelling & att. garage.		
ZONE R-1	OWNER	Robert E. Hanson	Clarksburg	
	ARCH'T	WY 1-2154		
	CONT'R	W. A. Rhoads	708-Q St.	Rio Linda
VAL. \$12,700.	STORIES 1	ROOMS 6	APTS. 550-gar.	SIZE 1,291 sq.ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	
FORM	7.5.62	Fully		
JOIST	7.7.62	Fully		
FRAME	8.10.62	Fully		
SHEET ROCK	8.22.62	Fully		
FINAL	10.15.62	Geo. Rife		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
7.11.62	Pl. Girt - Band joint insufficiently sealed. To seal on girdes joint Plumbing not completed. To seal a pipe. Filled
7.13.62	Pl. Girt - Numerous items Filled
7.23.62	Send notice to Contractor from
8.7.62	Pl. Frame - Numerous items Ribs
10.8.62	Pl. Gird - Show all girts must be tapered twice (mild) Ribs
	COMPLETE AND OK INSPECTOR