

R222 F402

Lot 1/43 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$55.00

Southgate Meadows #6 TYPE BUILDINGS R212 FS10-517

PERMIT NO. F-8192 LOCATION 7720 Quinby Way A-5

DATE Aug. 14/67 PURPOSE Const. dwelling & gara_e 101 LS
OWNER Valbrook 2777 Alvarado St., San Leandro

ZONE R-1 ARCH'T
CONTR Besco 2777 Alvarado St., San Leandro

VAL. \$15,100.	STORIES 1	ROOMS 5	APTS.	462 gar. SIZE 1,525 sq. ft.
----------------	-----------	---------	-------	--------------------------------

INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) 383-9315
-------	------	------------	-----------------	---------------------------

FORM	9.1.67	Larson		
------	--------	--------	--	--

JOIST	9.22.67	Larson		
-------	---------	--------	--	--

FRAME	10-25-67	Larson		
-------	----------	--------	--	--

SHEET ROCK	10-27-67	Larson		
------------	----------	--------	--	--

FINAL	1-9-68	[Signature]		
-------	--------	-------------	--	--

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
4.7.67	Pt Form - Cell in bottom of
	Form Lapsing
11.20.67	Pt membrane - Not ready Lapsing
9.24.67	ok seat Lapsing
10.20.67	Pt Frame - many minor items
	to correct Lapsing
10.22.67	Pt Frame - Correctors not made
	<p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>