

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-1939</i>	LOCATION <i>1907 - P Street</i>
DATE <i>8/22/34</i>	PURPOSE <i>Gen repairs to dwell. for</i>
ZON <i>Gen Com</i>	OWNER <i>for loss of Hawk</i>
	ARCH'T
	CONT'R <i>Julie Johnson & Son</i>
VAL. <i>1100⁰⁰</i>	STORIES
	ROOMS
	APTS.
	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
8/27/34	Made Preliminary check of Lower Flat
	Mantle damaged by fire. A.W. Campbell
9/5/34	2 ND INSP. Frame for Lower Flat ^{OK} A.W. Campbell
9/6/34	3 RD INSP. INT. WORK OK. A.W. Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>