

R-68

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD *FSEC*

TYPE BUILDINGS \$6.00

PERMIT NO. D-5368	LOCATION 919 Santa Ynez Way A-1
DATE Apr. 19, 60	PURPOSE Repair termite damage to dwelling
ZONE	OWNER H ertel
	ARCH'T
	CONT'R Valley termite 1617-13th St.

VAL. \$750.	STORIES	ROOMS	APTS.	SIZE
-------------	---------	-------	-------	------

INSP.	DATE	INSPECTOR
FORM	4-25-60	Shumway
JOIST		
FRAME	4-25-60	Shumway
LATH		
FINAL	5-4-60	Shumway

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
	COMPLETE AND OK INSPECTOR