

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS ~~R 10 15~~

PERMIT NO. <i>B-48174</i>	LOCATION <i>132 - San Antonio</i>			
DATE <i>2/18/47</i>	PURPOSE <i>Erect new dwlg. & garage</i>			
ZONE	OWNER <i>W.B. Phillips</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>6000⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>1130⁰⁰</i>	
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
2-19-47	R. G. Jones FORMS
6-28-47	" " " FRAME
7/25/47	" " " FINAL
	<p data-bbox="314 847 450 893">COMPLETE AND O. K.</p> <p data-bbox="1186 865 1327 888">INSPECTOR</p>