

## RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
4-24-73	Bldg. 400.00	A-3109 10.00	Repair Pest Damage	John Parker	Atox Termite 2259 Erickson St.	<i>Ridlo</i>	<i>2-27-74</i>
6-20-73	Elec. \$400.	A-5084 \$10.	New Elect Service Dwelling	S. Elliott	Warren Electric	Goodsell	7-9-73
1-16-68	Bldg. \$500.	F-9343 \$500.	Repair Termite Damage	W. C. Parker	Midstate Termite P. O. Box 8827	Larsen	3-12-68
3-1-79	BPE-\$2,800	G1845-\$80	Remodel bath	Arthur Dockter same as job	Owner	<i>Beals</i> <i>Herd</i>	<i>3-6-80 B</i> <i>2-21-80 P</i>
3/9/79	B. \$ 500.00	G-2040 \$ 20.00	Install 2 sliding glass doors in Dwlg	Art Dockter Same	Quality Exteriors Inc 1787 Tribute Rd. #J 95825	<i>Hilpin</i> <i>Beals</i>	<i>3/10/81 E</i> <i>5-6-80 B</i>
2-19-80	MPE \$6490.00	H-993 \$140.00	Install Heating & A/C Dwlg.	A/ Dockter Same	Trane Home Comfort 3270 Orange Grove	<i>Centrod</i> <i>Hilpin</i>	<i>4-8-80 pm</i> <i>3-3-80 E</i>

## MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
A-3109	<i>Q350 F591</i>	H-993	<i>R64 F302</i>		
<del>A-3109</del>	<del>R378 F149</del>	<del>H-993</del>	<del>R66 F291-282 final</del>		
A-5084	R-358 F 14				
A-5084	R-357 F 283	<i>H-2040</i>	<i>R66 F281 final</i>		
F-9343	R-231 F 459				
F	R-375 F 476	<i>G-1845</i>	<i>R66 F279-280 final</i>		
G-2040	<i>R561 F196</i>				
G-1845	<i>R559 F213-214</i>				

