

K2321243

Lot 927		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$49.00
Glenbrook Unit #9		TYPE BUILDINGS		R180 F276-287 R195 F308-313 REV R197 F553 REV.	
PERMIT NO.		LOCATION			
F-91116		52 - Waterglen Circle A-1 (52)			
DATE		PURPOSE			
1-31-68		Const. dwlg. & att. gar. #403			
ZONE		OWNER			
R-1		Anclas, Inc. 2777 Alvarado St. San Leandro, CAL.			
ARCH'T		CONTR			
		Besco same 383-9315			
VAL.		STORIES	ROOMS	APTS.	SIZE
\$13,800.					500 gar. 1394 sq.ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	3-28-68	Weld			
JOIST	3-7-68	Weld			
FRAME	4-15-68	Weld			
SHEET ROCK	4-18-68	Weld			
FINAL	3-20-69	Weld		Handwritten signature	

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
3-4-68	OK slab Risks
5-3-68	F+Ginal - Locked Risks
3-14-69	Will call per journal in 10 days
	1723869 Hammer
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div>