

*R-325 F138*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**\$12.00**

**TYPE BUILDINGS**

PERMIT NO. <b>H-6096</b>		LOCATION <b>131 - Sandburg Drive A-1</b>			
DATE <b>Mar. 30-72</b>		PURPOSE <b>Reroof dwelling</b>			
ZONE <b>R-1</b>		OWNER <b>Bill Morris, Jr. Same</b>			
		ARCH'T			
		CONT'R <b>Jack Goldston Rfg. Box 15095 Sacto.</b>			
VAL. <b>\$900.</b>		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C) <b>332 3475</b>
FORM					
JOIST					
FRAME					
SHEET ROCK					
<i>D-F</i> FINAL	<i>2-19-72</i>	<i>Dana Fuller</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR