

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|-----------------------------|---|
| PERMIT NO. <i>B-2184</i> | LOCATION <i>437 - Pala Way</i> |
| DATE <i>1/3/39</i> | PURPOSE <i>Erect new duplex garage</i> |
| ZONE <i>2-Fam</i> | OWNER <i>Wright Holding Co</i> |
| | ARCH'T. |
| | CONTR. <i>C. C. Ruby</i> |

| | | | | |
|------------------|---------------------|-------------------|-------------------|------|
| VAL. <i>3000</i> | STORIES <i>1</i> | ROOMS <i>5</i> | APTS. <i>2</i> | SIZE |
|------------------|---------------------|-------------------|-------------------|------|

| | | | |
|-------------------|--|------------------|---|
| LIGHT SHAFTS | | ELEVATOR SHAFTS | <i>Area 850^{sq} 2350 /</i> |
| VENT SHAFTS | | BOILER ROOMS | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | |
| LATH | | GAS VENTS | |
| FIRE ESCAPES | | CHIMNEYS | |
| STAND PIPES | | SKYLIGHTS | |

| DATE | CONDITION OF WORK—REMARKS |
|---------|--|
| 1/6-38 | 15' Deep Forms or Piles |
| 7/14-39 | 2 " Frame " Piles |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <div style="display: flex; justify-content: space-between;"> COMPLETE AND C. R. INSPECTOR </div> |