

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA														
PROPERTY PARCEL NO.										JOB ADDRESS				
8665 Fallbrook Way										INSPECTION AREA				
LEGAL DESCRIPTION										BUILDING BY				
Lot 280 Glenbrook #3										Larsen				
TITLE AND NAME										DATE				
GEN. CONTR. Beasco										ELECTRICAL BY				
ELEC. CONTR.										DATE				
PLBG. CONTR.										PLUMBING BY				
MECH. CONTR.										DATE				
ARCH. ENGR.										MECHANICAL BY				
OWNER Estructures, Inc.										DATE				
CONST. LOAN LENDER										CERTIFICATE OF OCCUPANCY				
2777-Alvarado St.										ISSUED BY				
BLDG. WIDTH										DATE				
BLDG. LENGTH										TOTAL AREA				
NO. OF STORIES										C.S.D.				
ROOMS R.										C.I. CASE				
AREA 1st FLOOR										EXISTING BLDG'S SAME LOT				
446-gar. 1,593 sq. ft.										HOW USED				
SPACES										REAR YARDS				
TREES RMVD.										SET BACK REQ.				
PARK'G REQ.										USE ZONE				
5										1				
446-gar.										PARK'G REQ.				
REAR YARDS										SET BACK REQ.				
SIDE YARDS										REAR YARDS				
NATURE OF WORK:- Const. dwelling & garage Plan 604 A														
PERMIT NO. S.P. - F-3711														
ISSUED BY														
ISSUANCE DATE 4/6/66														
PLANS AND APPLICATION														
REEL NO. 191 FRAME NO. 280 TO														
INSPECTION RECORD														
REEL NO. 191 FRAME NO. 271 TO														
JOB FILE														
R.U.F. FEE \$														
S.M.I. FEE \$														
PLAN CK. FEE \$														
SEWER INCL. FEE \$														
PERMIT FEE \$ 55.00														
TOTAL FEES \$														
REMARKS AND/OR VARIANCES														
DWEILING														

8665 - Fallbrook Way