

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>3314</i>	LOCATION <i>3809 2 Ave.</i>		
DATE <i>9/10/28</i>	PURPOSE <i>Repair</i>	ROOMS	APTS.
ZONE	OWNER <i>Carlford</i>	PHONE	
	ARCHT		
	CONTR <i>Walter Thompson Co</i>		
	VAL. <i>221 W</i>	STORIES <i>0</i>	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF			
Ex Wall	Jolsts						Chimneys		Cement Tests
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS

**COMPLETED
AND O. K.**

INSPECTOR