

*5130768*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**\$5.00**

**TYPE BUILDINGS**

PERMIT NO. <b>E-5327</b>		LOCATION <b>337 - Santa Ynez Way</b>		A-1	
DATE <b>Oct. 15-63</b>		PURPOSE <b>Repair rot damage to dwelling</b>			
ZONE <b>R-1</b>		OWNER <b>H. H. Johnson</b>		Same	
		ARCH'T			
		CONT'R <b>Valley Termite</b>		<b>1617 - 18th Street</b>	
VAL. <b>\$200.</b>		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM					
JOIST					
FRAME	<i>10-17-63</i>	<i>Count</i>			
SHEET					
ROCK					
FINAL	<i>10-29-63</i>	<i>Count</i>			

*pc*



DATE

SPECIAL CONDITIONS OF WORK — REMARKS

10/22/63 Pt job incomplete Buckets

COMPLETE  
AND OK

INSPECTOR