

5130768

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$5.00

TYPE BUILDINGS

PERMIT NO. E-5327		LOCATION 337 - Santa Ynez Way		A-1	
DATE Oct. 15-63		PURPOSE Repair rot damage to dwelling			
ZONE R-1		OWNER H. H. Johnson		Same	
		ARCH'T			
		CONT'R Valley Termite		1617 - 18th Street	
VAL. \$200.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM					
JOIST					
FRAME	<i>10-17-63</i>	<i>Count</i>			
SHEET					
ROCK					
FINAL	<i>10-29-63</i>	<i>Count</i>			

pc



DATE

SPECIAL CONDITIONS OF WORK — REMARKS

10/22/63

Pt job incomplete Buckets

COMPLETE
AND OK

INSPECTOR