

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. 6141-A LOCATION 1018 - 2<sup>ND</sup> ST  
 DATE 4/19/37 PURPOSE Make repairs to floor  
 OWNER Sunnyside Cafe  
 ZONE Gen Com ARCH'T.  
 CONTR. J. F. Reynolds 415-T/20

VAL. 4600? STORIES ROOMS APTS. SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE

CONDITION OF WORK—REMARKS

~~4/21/37~~

Made adjustments of repairs to main  
 floor. Park in center section replaced  
 with new T & G. Flooring  
 O. K. H. Campbell

4/21/37

COMPLETE  
AND O. K.

H. Campbell

INSPECTOR