

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-6991</i>	LOCATION <i>531- Santa Ynez Way</i>
DATE <i>9/18/37</i>	PURPOSE <i>Reskinning of</i>
ZONE	OWNER <i>Paul Geisler</i>
	ARCH'T.
	CONT'R. <i>Pacific Roofing Co.</i>

VAL. <i>12000</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="349 837 474 878">COMPLETE AND O. K.</p> <p data-bbox="1171 857 1297 878">INSPECTOR</p>