

| | | | | |
|----------------|----------------|---|-----------------|--------------------------------------|
| Lot 319 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | \$46.00 |
| Glenbrook #3 | | TYPE BUILDINGS <i>R1B0 F380</i> <i>R1B0 F480-489</i> | | |
| PERMIT NO. | | | | |
| F-3501 | LOCATION | 2819 - Sandbrook Court | | A-1 |
| DATE | PURPOSE | Const. dwlg. & att. gar. Plan 401 LB | | |
| Mar 21-66 | OWNER | Valbrook, Inc. 2777-Alvarado St., | | |
| ZONE | ARCH'T | /San Leandro | | |
| R-1 | CONTR | Besco same 363-7315 | | |
| VAL. \$12,400. | | STORIES | ROOMS | APTS. 494-gar. SIZE 1,232 sq. ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | <i>3-30-66</i> | <i>Chippin</i> | | |
| JOIST | <i>4-8-66</i> | <i>Hammons</i> | | |
| FRAME | <i>4-28-66</i> | <i>Hammons</i> | | |
| SHEET ROCK | <i>5-5-66</i> | <i>Hammons</i> | | |
| FINAL | <i>6-17-66</i> | <i>E. Hammond</i> | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|-----------------|--|
| 3-29-66 | Pt. from. No plans on file. <i>Wanna</i> |
| 4-30-66 | Pt. from. - Not ready. <i>Wanna</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |