

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-1431</i>	LOCATION <i>1400 - P M</i>
DATE <i>10/9/45</i>	PURPOSE <i>Remodel attic for room</i>
ZONE	OWNER <i>M. Roush</i>
	ARCH'T.
	CONT'R. <i>[Signature]</i>

VAL. <i>1000</i>	STORIES	ROOMS	PTS.	SIZE
------------------	---------	-------	------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
10/11/45	<p>Made Preliminary Insp with Housing Committee of proposed remodeling of Attic for 5 Pass with new Outside Stairways from pass to ground on rear of bldg for <u>2nd Exit</u> <u>W Campbell</u></p>
7/26/46	<p>Frame Insp. in Attic C.E. Puckins</p>
	<p>COMPLETE AND O. K. INSPECTOR</p>