

R 3310 F67

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$30.00

TYPE BUILDINGS

| | | | | |
|------------------------|--|--------------------|--------------------|---------------|
| PERMIT NO. H-8653 | LOCATION 349 4 - Taylor Street | A-6 | | |
| DATE Sept. 7-72 | PURPOSE Repairs to dwelling | | | |
| ZONE R-1 | OWNER St. Marks Church | 2391-St. Marks Wy. | | |
| | ARCH'T | | | |
| | CONT'R | Owner | Same | 483 7848 |
| VAL. \$3,500. | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | | | | |
| JOIST | | | | |
| FRAME SHEET ROCK | 11-2-72 | Count | | |
| FINAL | | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |