

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>13-2878</i>	LOCATION <i>560 - San Antonio Way</i>
DATE <i>4/18/39</i>	PURPOSE <i>Erect new dwlg. gas</i>
ZONE <i>2-7am</i>	OWNER <i>E. P. Mason</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>45000</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	<i>123/PI</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 200</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
5-1-39	1 <sup>st</sup> Ins p forms ok Quiter
6/23/39	2 <sup>nd</sup> / NSP. Frame in place of Mr Campbell
	2 <sup>nd</sup> " Int East Side " Quiter
9-12-39	4 Ins p framed ok Quiter
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="329 878 461 919">COMPLETE AND O. K.</span> <span data-bbox="1206 891 1347 915">INSPECTOR</span> </div>