

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-7058</i>	LOCATION <i>1314 - Tenenight Way</i>
DATE <i>9/25/37</i>	PURPOSE <i>Erect new dwl. & garage</i>
ZONE	OWNER <i>G. Bruce Asbury</i>
	ARCH'T.
	CONTR. <i>G. Bruce Asbury</i>

VAL. <i>5000⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>1500⁰⁰</i>	
VENT SHAFTS		BOILER ROOMS	<i>@ 350</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>1</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
9/27/37	1 ST INSPECTION. Formwork in place ^{OK} A.W. Campbell
10-18 37	2 ND " Frame. " P.H. [unclear]
11/15/37	3 RD INSPECTION. INT & EXT. WORK ^{OK} A.W. Campbell
12/20/37	4 TH INSPECTION. Dwg & [unclear] Complete ^{OK}
	A.W. Campbell
" "	Issued Final Insp. & Certificate of Occupancy
" "	Sheets Cleaned up ^{OK}
12/20/37	COMPLETE AND O. K. <u>A.W. Campbell</u> INSPECTOR