

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|-----------------------------------|---|
| PERMIT No. A-1398 | LOCATION 3151 Y ST. |
| DATE FEB. 15 1934 | PURPOSE Make Alterations & Repairs to Interior of Dwlg. |
| ZONE LIMITED RETAIL | OWNER DAVID THOMAS. 3151 Y ST. |
| | ARCH'T |
| | CONT-R W. B. LA DUE. 2319 O. ST. |

VAL.

300⁰⁰

STORIES

1

ROOMS

APTS.

SIZE

| | | | |
|-------------------|--|------------------|--|
| Light Shafts | | Elevator Shafts | |
| Vent Shafts | | Boiler Rooms | |
| Owner's Inspector | | Sprinkler System | |
| Lath | | Gas Vents | |
| Fire Escapes | | Chimneys | |
| Stand Pipes | | Skylights | |

| DATE | CONDITION OF WORK—REMARKS |
|------|---|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND O. K. INSPECTOR |