

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO.

LOCATION

913-16

1447

PURPOSE

Sign

PHONES

DATE

OWNER

W. J. Rudman & Sons

ARCHIT

ISSUED
ZONE 13 1927
SACRAMENTO CENTER
BUILDING DIVISION

VAL.

324

STORIES

ROOMS

APTS.

SIZE

Steel Tested by

Elevator Shafts

Cement Tested by

Boiler Rooms

Owner's Inspector Rfcd. Conc.

Sprinkler System

Floor Tests

Fire Escapes

Stand-pipes

DATE

CONDITION OF WORK—REMARKS

**COMPLETED
AND O. K.**

Inspector