

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>No Charge</i>	LOCATION <i>811-14<sup>th</sup> St.</i>
DATE <i>Dec 9<sup>th</sup> 1931</i>	PURPOSE <i>We have one old record with Compton Park in</i>
ZONE <i>General Commercial</i>	OWNER <i>H. H. Crawford. 811-14<sup>th</sup> St.</i>
	ARCH'T
	CONT-R <i>Owner</i>

VAL. <i>600<sup>00</sup></i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
---------------------------------	---------------------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Poles		Skylights	

DATE

CONDITION OF WORK-REMARKS

10/9/31

Gave man on job this No Charge Permit for  
application with composition roofing directly  
over old shingled roof. Man said this  
was only intended as a temporary roof as  
owner intended to put a more permanent  
roof on next year. R. W. Campbell

COMPLETE  
AND O.K.

INSPECTOR

## APPLICATION FOR PERMIT TO BUILD

Street No. 811-14th Lot \_\_\_\_\_ Block H.I.-14,15.

Owner Miss Couch. Address \_\_\_\_\_

Architect \_\_\_\_\_ Address \_\_\_\_\_

Contractor B. A. Gardner. Address Del Paso Heights.

Kind of Building \_\_\_\_\_

Foundation One city for dwelling

Posts \_\_\_\_\_ Girder \_\_\_\_\_ Span \_\_\_\_\_ Mud Sills \_\_\_\_\_

PERMIT
DATE
<u>9/26/16</u>
DISTRICT

	1ST FLOOR	2ND FLOOR	3RD FLOOR	4TH FLOOR	5TH FLOOR	6TH FLOOR
Joists						
Max. Span						
Bearing Partitions	<u>Repair the front steps.</u>					
Non-bearing Partitions						
Story Heights						
Outside Walls						
Ceiling Joists			Span			
Roof			Rafters			
Water Heater			Chimney			
Size of Building—Length			Width			Height

It is hereby agreed that this building will be constructed in conformity with the Ordinances of the City of Sacramento and the Laws of the State of California.

Estimated cost, \$ 2000  
 Plans must be submitted.

B. A. Gardner  
 Owner or Owner's Representative.

