

911 723-28

|               |           |  |                 |       |                                     |
|---------------|-----------|--|-----------------|-------|-------------------------------------|
| Pt. 43        |           | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD |                 |       | \$55.00                             |
| Southfield #1 |           | TYPE BUILDINGS                                       |                 |       | B11 741                             |
| PERMIT NO.    |           |  |                 |       | A-5                                 |
| E-2668        | LOCATION  |  |                 |       | 7522-Tamoshanter Way & 7520-Skelton |
| DATE          | PURPOSE   | Const. duplex & att. gar.                            |                 |       | Plan 1648                           |
| Nov. 13-62    | OWNER     | Maybell Enterprises                                  |                 |       | 3200-Fulton Ave                     |
| ZONE          | ARCH'T    | 483-4391   |                 |       |                                     |
| R-1           | CONTR     | World Const. Box 542-Carmichael                      |                 |       |                                     |
| VAL.          | \$15,600. | STORIES  | ROOMS           | APTS. | 625-gar. SIZE                       |
|               |           | 1  | 8               |       | 1,648 sq. ft.                       |
| INSP.         | DATE      | BLDG. TYPE   | OCCUPANCY GROUP |       |                                     |
| FORM          | 11-19-62  | Rich   |                 |       |                                     |
| JOIST         | 1-28-62   | Fuller   |                 |       |                                     |
| FRAME         | 12-31-62  | Hanson   |                 |       |                                     |
| SHEET ROCK    | 1-3-63    | Caputo   |                 |       |                                     |
| FINAL         | 2-14-63   | Geo. Perls   |                 |       |                                     |

| DATE            | SPECIAL CONDITIONS OF WORK — REMARKS  |
|-----------------|---|
| 11-26-62        | <p> <i>           All bolts must be in center of mudsill<br/>           exist not 4" oc Poor concrete,<br/>           poor in garage area bolts         </i> </p> |
| 12-27-62        | <p> <i>           1 X 4 Braces notched too shch.<br/>           P.T. fire block missing Roof not complete, fire wall not framed right         </i> </p>           |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
| COMPLETE AND OK | INSPECTOR   |