

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 147-Glenville Circle		INSPECTION AREA 1	
LEGAL DESCRIPTION Lot 1110 Glenbrook #11					
TITLE AND NAME Besco		ADDRESS 2777-Alvarado Street		ZIP	CITY LIC. NO.
GEN. CONTR.		ELEC. CONTR.		ELECTRICAL BY DATE	
PLBG. CONTR.		MECH. CONTR.		PLUMBING BY DATE	
ARCH. ENGR.				MECHANICAL BY DATE	
OWNER Sonya Corp.		2777-Alvarado Street San Leandro			
CONST. LOAN LENDER		CERTIFICATE OF OCCUPANCY			
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR
TOTAL AREA		C.S.D.	C.I. CASE	ISSUED BY DATE	
475-Garage 1,593 sq. ft.		CENSUS TRCT. NO.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES
TREES RMVD.		EXISTING BLDG'S SAME LOT		HOW USED	

NATURE OF WORK:- Const. dwelling & garage MP#604

PERMIT NO. S.P. - G-8649		ISSUED BY		ISSUANCE DATE 10/5/70	
VALUATION		\$ 24,000.00		PLANS AND APPLICATION	
RD. F. FEE		\$		REEL NO. 289	
S.M.I. FEE		\$		FRAME NO.- 211	
PLAN CK. FEE		\$		TO	
SEWER INCL. FEE		\$		FRAME NO.- 271	
PERMIT FEE		\$ 86.00		TO	
TOTAL FEES		\$		FRAME NO.- 553	
		\$		REEL NO. 197	
		\$		JOB FILE	
		\$		REEL NO. 191	
		\$		FRAME NO.- 276	
		\$		TO	
		\$		ceiling	
		\$		REMARKS AND/OR VARIANCES	
		\$		DWEELLING	
		\$		8507P646 - final	
		\$		MICROFILM RECORD	