

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4490</i>	LOCATION <i>2330 - P.H.</i>
DATE <i>12/20/39</i>	PURPOSE <i>Erect new dwlg a/g</i>
ZONE	OWNER <i>Dr. Jgo Fletcher</i>
	ARCH'T. <i>N. H. Lund.</i>
	CONTR. <i>N. H. Lund.</i>

VAL. <i>12,000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>12</i>	APTS <i>4</i>	SIZE
---------------------------------	---------------------	--------------------	------------------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS	BOILER ROOMS	<i>3026<sup>00</sup></i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>@ 4'-0"</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
12	15 Insp Frames of Register
2-20-40	2 <sup>nd</sup> Insp Frame of Register
	<p data-bbox="332 1065 483 1114"><b>COMPLETE AND O. K.</b></p> <p data-bbox="1330 1086 1491 1111"><b>INSPECTOR</b></p>