

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | |
|-------------------------------|---|------------------|-------|------|
| PERMIT NO. <i>B-12509</i> | LOCATION <i>2535 - 5th Street</i> | | | |
| DATE <i>7/21/44</i> | PURPOSE <i>General repairs</i> | | | |
| ZONE | OWNER <i>Erskine Hatcher</i> | | | |
| | ARCH'T. | | | |
| | CONTR. <i>Bingham Const. Co.</i> | | | |
| VAL. <i>1500⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
| LIGHT SHAFTS | | ELEVATOR SHAFTS | | |
| VENT SHAFTS | | BOILER ROOMS | | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | | |
| LATH | | GAS VENTS | | |
| FIRE ESCAPES | | CHIMNEYS | | |
| STAND-PIPES | | SKYLIGHTS | | |

| DATE | CONDITION OF WORK-REMARKS |
|---------|---|
| 8/18/44 | Made inspection of general repairs to interior & exterior of building for Hatching |
| | O. K. A. W. Campbell |
| | |
| | |
| | |
| | |
| | |
| | |
| 8/18/44 | COMPLETE AND O. K. <i>A. W. Campbell</i> INSPECTOR |

