

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-33572</i>	LOCATION <i>4040-2nd Ave</i>
DATE <i>9/26/51</i>	PURPOSE <i>Repair garage roof</i>
ZONE	OWNER <i>E. R. Jinsley</i>
	ARCH'T.
	CONTR. <i>J. P. Howell</i>

VAL. <i>2300</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="309 881 450 927">COMPLETE AND O. K.</p> <p data-bbox="1241 902 1388 927">INSPECTOR</p>