

R 259 F 569

Lot #588 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$40.00

Southgate Meadows #7 TYPE BUILDINGS R 259 F 553-556

| | |
|----------------------|--|
| PERMIT NO. G-3356 | LOCATION 43 - Thatcher Circle A-5 (49) |
| DATE May-8-69 | PURPOSE Const. dwelling & att. garage MP#1002 |
| ZONE R-1 | OWNER Center Dev., Inc. 2777 - Alvarado St. |
| | ARCH'T 383-9315 |
| | CONTR Besco Same San Leandro, Cal. |

| | | | | |
|----------------|--------------|------------|-------------------|----------------------|
| VAL. \$10,900. | STORIES 1 | ROOMS 5 | APTS. 340-gar. | SIZE 1,166 sq ft. |
|----------------|--------------|------------|-------------------|----------------------|

| | | | | |
|-------|------|------------|-----------------|---------------|
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
|-------|------|------------|-----------------|---------------|

| | | | | |
|------|---------|--------|--|--|
| FORM | 5-15-69 | Miller | | |
|------|---------|--------|--|--|

| | | | | |
|-------|--|--|--|--|
| JOIST | | | | |
|-------|--|--|--|--|

| | | | | |
|-------|---------|--------|--|--|
| FRAME | 5-16-69 | Miller | | |
|-------|---------|--------|--|--|

| | | | | |
|---------------|---------|--------|--|--|
| SHEET ROCK | 5-26-69 | Miller | | |
|---------------|---------|--------|--|--|

| | | | | |
|-------|---------|---------|--|--|
| FINAL | 8-29-69 | Collins | | |
|-------|---------|---------|--|--|

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|------|--------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |
| | INSPECTOR |