

| | | | | | |
|----------------|----------------|--------------------------------------------------------------|-----------------|---------------|--------------|
| Lot 314 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$52.00 | | | |
| Glenbrook #3 | | TYPE BUILDINGS <i>B189 7392</i> <i>R180 7265-2720</i> | | | |
| PERMIT NO. | | | | | |
| F-3514 | LOCATION | 2841 - Sandbrook Court | | A-1 | |
| DATE | PURPOSE | -Const. dwlg. & att. gar. Plan 404 IC | | | |
| Mar 21-66 | OWNER | Brookvale, Inc. 2777-Alvarado St., San | | | |
| ZONE | ARCH'T | /Leandro | | | |
| R-1 | CONTR | Besco same 363-7315 | | | |
| VAL. \$14,800. | | STORIES | ROOMS | APTS. | SIZE |
| | | | | 462-gar. | 1523 sq. ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | <i>3-30-66</i> | <i>Chapin</i> | | | |
| JOIST | <i>4-4-66</i> | <i>Hammers</i> | | | |
| FRAME | <i>4-31-66</i> | <i>Hammers</i> | | | |
| SHEET ROCK | <i>4-29-66</i> | <i>Chapin</i> | | | |
| FINAL | <i>6-16-66</i> | <i>E. Hammers</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|--------------------|-------------------------------------------|
| 3-29-66 | Pt from - No plans on file <i>Hammers</i> |
| 3-31-66 | Ok membrane <i>Hammers</i> |
| 4-1-66 | Ok membrane <i>Hammers</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |