

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-5690</i>	LOCATION <i>1208 - Swanton Dr.</i>			
DATE <i>6/3/40</i>	PURPOSE <i>New dwlg.</i>			
ZONE <i>—</i>	OWNER <i>Frank Dittler -</i>			
	ARCH'T. <i>L. G. Daddemi -</i>			
	CONTR. <i>L. G. Daddemi -</i>			
VAL. <i>6700⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>2</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1678⁰¹</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 3⁰⁰</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
6/1/40	1 ST INSP. Forme in place ^{OK} <i>Mr Campbell</i>
7/24-40	2 ND Insp Forme ^{OK} <i>Director</i>
11/40	3 RD INSP. INT & EXT LATH ^{OK} <i>Mr Campbell</i>
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>