

R232 F239

Lot 921		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$55.00
Glenbrook Unit #9		TYPE BUILDINGS		<i>R191 F271-276</i> <i>R197 F553 REV.</i>	
PERMIT NO. F-9439	LOCATION 28 - Waterglen Circle A-1 (52)				
DATE 1-31-68	PURPOSE	Const. dwlg. & att. gar. #604			
ZONE R-1	OWNER	Valbrook, Inc. 2777 Alvarado St. San Leandro, CAL			
	ARCH'T				
	CONTR	Besco Same 383-9315			
VAL. \$15,600.	STORIES	ROOMS	APTS.	475 gar. SIZE 1593 sq.ft.	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	<i>2-15-68</i>	<i>Luxon</i>			
JOIST	<i>7</i>	<i>Walsh</i>			
FRAME	<i>4-9-68</i>	<i>Field</i>			
SHEET ROCK	<i>4-11-68</i>	<i>Chapin</i>			
FINAL	<i>5-28-68</i>	<i>Field</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
8-23-68	Pt slab - No sit work. Not a
	Crushed rock in slab. Pts
2-29-68	Pt slab. Cant
3-5-68	Pt joint. Not ready. Pts
COMPLETE AND OK	INSPECTOR