

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA		FINAL INSPECTIONS	
3621 Clay Street				6			
LEGAL DESCRIPTION		OCCUP. GR.		CONST TYPE		VAR. NO.	
Lot 11 Block 28 Rancho Del Paso							
TITLE AND NAME		ADDRESS		CITY LIC. NO.		TEL. NO.	
Sistler Const. Co		2223 Dale Ave.					
GEN. CONTR.		ELECTRICAL BY		DATE			
Sistler Const. Co		2223 Dale Ave.					
ELEC. CONTR.		PLUMBING BY		DATE			
Sistler Const. Co		2223 Dale Ave					
PLBG. CONTR.		MECHANICAL BY		DATE			
Sistler Const. Co		2223 Dale Ave					
MECH. CONTR.		CERTIFICATE OF OCCUPANCY		ISSUED BY		DATE	
Sistler Const. Co							
ARCH. ENGR.		CONST. LOAN LENDER		BLDG. WIDTH		BLDG. LENGTH	
				TOTAL HEIGHT		NO. OF STORIES	
				ROOF CONSTR.		AREA 1st FLOOR	
				TOTAL AREA		C.S.D.	
				C.I. CASE			
				EXISTING BLDG'S SAME LOT		HOW USED	
				480 gar			
				TRES RMVD.		SPACES	
				REAR YARDS		SET BACK REQ.	
				USE ZONE		PARK'G REQ.	
				SIDE YARDS		NATURE OF WORK:-	
				Const. dwelling & attached garage		1,423 sq. ft.	
PERMIT NO. S.P. H-5027		MICROFILM RECORD		ISSUED BY		12-30-71	
VALUATION		PLANS AND APPLICATION		REEL NO. 319		FRAME NO. 90	
\$20,600		INSPECTION RECORD		REEL NO.		FRAME NO. TO	
R.O.F. FEE		JOB FILE		REEL NO.		FRAME NO. TO	
\$		S.M.I. FEE		PLAN CK. FEE		SEWER INCL. FEE	
\$		PERMIT FEE		\$81.00		TOTAL FEES	
\$		REMARKS AND/OR VARIANCES					