

Bldg 7477-4R3

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$79.00

Lot 75

Southland Park Hills Unit #29 **TYPE BUILDINGS**

PERMIT NO. E-9820	LOCATION: & 7355 South Land Park Dr. 7353 - Southland Park Drive			
DATE Mar. 5-65	PURPOSE Const. duplex and att. garages			
OWNER Frank Schiro	ARCH'T / 483-8103			
ZONE R-1	CONT'R Lyndel Builders 2849 - Fulton Ave			
VAL. \$23,700.	STORIES 1	ROOMS 10	APTS. 2-sq. footage 2,524 sq. ft.	\$2500
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM	3-10-65	Peris		
JOIST	3-19-65	Mr. Calloway		
FRAME	4-14-65	Mr. Calloway		
SHEET ROCK	4-19-65	<del>Mr. Calloway</del>		
FINAL	6-11-65	<del>Mr. Calloway</del>		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
4-17-65	P.T. Frame 1 X 4 missing top of 2X6 ceiling joist. <span style="float: right;">M. Colson</span>
6-7-65	P.T. - final locked <span style="float: right;">Court</span>
	<div style="display: flex; justify-content: space-between;"> <span><b>COMPLETE AND OK</b></span> <span><b>INSPECTOR</b></span> </div>