

Bldg 7477-4R3

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$79.00

Lot 75

Southland Park Hills Unit #29 **TYPE BUILDINGS**

| | | | | |
|----------------------|---------------------------------------------------------------------|-------------------------|-----------------------------------------|---------------|
| PERMIT NO. E-9820 | LOCATION: & 7355 South Land Park Dr. 7353 - Southland Park Drive | | | |
| DATE Mar. 5-65 | PURPOSE Const. duplex and att. garages | | | |
| ZONE R-1 | OWNER Frank Schiro | | | |
| | ARCH'T / 483-8103 | | | |
| | CONT'R Lyndel Builders 2849 - Fulton Ave | | | |
| VAL. \$23,700. | STORIES 1 | ROOMS 10 | APTS. 2-sq. footage 2,524 sq. ft. | \$2500 |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | 3-10-65 | Peris | | |
| JOIST | 3-19-65 | Mr. Calloway | | |
| FRAME | 4-14-65 | Mr. Calloway | | |
| SHEET ROCK | 4-19-65 | Mr. Calloway | | |
| FINAL | 6-11-65 | Mr. Calloway | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|---------------------------------------------------------------------------------------------------------------------|
| 4-17-65 | P.T. Frame 1 X 4 missing top of 2X6 ceiling joist. <i>M. Colson</i> |
| 6-7-65 | P.T. - final locked Court |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p data-bbox="293 857 431 919">COMPLETE AND OK</p> <p data-bbox="1213 888 1356 919">INSPECTOR</p> |