

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 1968-A	LOCATION 1537 - Santa Vnez Way
DATE 8/31/34	PURPOSE To add small play room office
ZONE C	OWNER I - Nairn's
	ARCH'T
	CONT'R O'Connell

VAL. 250 ⁰⁰	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
9/4/34	Made Frame Joints for installing Play Room in Kibbi with plumbing & floor O.K. W. Campbell
9/4/34	3 rd N.S.P. Int. Lat. OK W. Campbell
9/18/34	4 th N.S.P. Plug hole in Kibbi completed
9/18/34	COMPLETE AND O.K. <i>Walter H. Campbell</i> INSPECTOR