

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2056</i>	LOCATION <i>3734 - San Carlos Way</i>			
DATE <i>12/7/38</i>	PURPOSE <i>Erect new dwlg. for</i>			
ZONE	OWNER <i>Dorothy Pierce</i>			
	ARCH'T.			
	CONTR. <i>H. L. Pierce</i>			
VAL. <i>3500⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>860⁰'</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 35⁰</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
1-2-12-38	18 ⁵ Insp Forms of Pictur
	COMPLETE AND O. K. INSPECTOR