

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA		FINAL INSPECTIONS	
		3801 Bigler Way					4-C			
LEGAL DESCRIPTION		OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY		DATE		
TITLE AND NAME		1/C	ADDRESS	ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY		DATE	
GEN. CONTR.							PLUMBING BY		DATE	
ELEC. CONTR.							MECHANICAL BY		DATE	
PLBG. CONTR.							CERTIFICATE OF OCCUPANCY			
MECH. CONTR.							ISSUED BY		DATE	
ARCH. ENGR.										
OWNER										
CONST. LOAN LENDER										
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
							CENSUS TRCT. NO.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:-

PERMIT NO. S.P. -		MICROFILM RECORD			
ISSUED BY					
ISSUANCE DATE	PLANS AND APPLICATION	REEL NO.	FRAME NO.:-	TO	
VALUATION \$	INSPECTION RECORD	REEL NO.	FRAME NO.:-	TO	
R.D.F. FEE \$	JOB FILE	REEL NO.	FRAME NO.:-	TO	
S.M.I. FEE \$					
PLAN CK. FEE \$					
SEWER INCL. FEE \$					
PERMIT FEE \$	REMARKS AND/OR VARIANCES				
\$					
\$					
TOTAL FEES \$					

3801 Bigler Way

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
4/28/77	Wreck	W-7318 \$ 20.00	Wreck	Water West Service Inc. Owner 1919 21st Street Suite #209		<i>Shuler</i>	4-28-77
4-12-23	B. \$50.	3961 \$1.	Fr. 1-story dwelling	Bertha Maganda	0 S Becker 3801 Bigler Way		
7-23-51	B. \$50.	No Charge	Change roof rear dwlg.	G.J. Mansfield	Owner		
MICROFILM RECORD							
PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
W-7318 3961 4/1-7318 N.D. 419	RA80F 349 RA82F 464 RA85F 458 RA85F 458 RA85F 458						