

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA		FINAL INSPECTIONS	
3621 Clay Street				6			
LEGAL DESCRIPTION		OCCUP. GR.		CONST TYPE		VAR. NO.	
Lot 11 Block 28 Rancho Del Paso							
TITLE AND NAME		ADDRESS		CITY LIC. NO.		TEL. NO.	
Sistler Const. Co		2223 Dale Ave.					
GEN. CONTR.		ELECTRICAL BY		DATE			
Sistler Const. Co		2223 Dale Ave.					
ELEC. CONTR.		PLUMBING BY		DATE			
Sistler Const. Co		2223 Dale Ave					
PLBG. CONTR.		MECHANICAL BY		DATE			
Sistler Const. Co		2223 Dale Ave					
MECH. CONTR.		CERTIFICATE OF OCCUPANCY		ISSUED BY		DATE	
Sistler Const. Co		2223 Dale Ave					
ARCH. ENGR.		OWNER		CONST. LOAN LENDER			
Sistler Const. Co		2223 Dale Ave					
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT		NO. OF STORIES	
SIDE YARDS		REAR YARDS		SET BACK REQ.		USE ZONE	
NATURE OF WORK:-		Const. dwelling & attached garage					
1,423 sq. ft.							
SIDE YARDS		TREES RMVD.		SPACES		ROOF CONSTR.	
480 gar							
EXISTING BLDG'S SAME LOT		C.S.D.		TOTAL AREA		AREA 1st FLOOR	
HOW USED		C.I. CASE		CENSUS TRCT. NO.		AREA 1st FLOOR	
ISSUANCE DATE		VALUATION		R.O.F. FEE		S.M.I. FEE	
12-30-71		\$20,600		\$		\$	
PLANS AND APPLICATION		INSPECTION RECORD		JOB FILE		REMARKS AND/OR VARIANCES	
REEL NO. 319		FRAME NO. 90		TO 96			
REEL NO.		FRAME NO.		TO			
REEL NO.		FRAME NO.		TO			
PLAN CK. FEE		SEWER INCL. FEE		PERMIT FEE		TOTAL FEES	
\$		\$		\$81.00		\$	
MICROFILM RECORD							
ISSUED BY		PERMIT NO. S.P. H-5027					
12-30-71							