


BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>8695</i>	LOCATION <i>64 Land Dr. Terrace 1116 Parkside Way</i>
DATE <i>10/5/31</i>	PURPOSE <i>Fully Occupied</i>
ZONE <i>2-Ton</i>	OWNER <i>W. B. Phillips</i>
	ARCHT <i>W. B. Phillips</i>
	CONT-R <input checked="" type="checkbox"/>
	PHONES

VAL. <i>5000</i>	STORIES <i>1</i>	ROOMS <i>7</i>	APTS. <i>1</i>	SIZE <i>39 x 45 - 25</i>
---------------------	---------------------	-------------------	-------------------	-----------------------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
10-5-31	1 st Insp Forms on P.H. Routes
10/29-31	2 " Forms " P.H. Routes
11/3-31	3 cc Int & Ext Sectors P.H. Routes
12/18-31	4 " Finalized OK
	Certificate of occupancy issued OK
	<div style="display: flex; justify-content: space-between; align-items: center;"> COMPLETE AND O.K. <div data-bbox="584 809 1197 976" style="text-align: center;">  </div> INSPECTOR </div>